

Komatsu D65PX-18

Bulldozer · Construction

BRAND

Komatsu

MODEL

D65PX-18

YEAR

2019

SERIAL NO.

D65PX-A00123

ENGINE HOURS

6,840 hrs

HRS SINCE

SERVICE

410 hrs

YARD LOCATION

Tema, Ghana

OVERALL ASSESSMENT

Wear Detected

5 components inspected

COMPONENT WEAR ANALYSIS

COMPONENT	CONDITION STATUS
Blade	Good
Hydraulics	Excellent
Final Drive	Good
Engine Block	Excellent
Undercarriage	Wear Detected

INSPECTION NOTES

Low-ground-pressure dozer in strong working condition. Recent undercarriage inspection completed. Suitable for earthmoving and land clearing.

This inspection report documents the physical condition of the listed equipment as assessed by BlueRock Equipment's yard inspection team. All component ratings reflect visual inspection and operational testing completed on the inspection date above. This report is valid for 90 days.

CERTIFIED BY

BlueRock Equipment

Yard Inspection Division